



Republic of the Philippines
TARLAC STATE UNIVERSITY
Romulo Blvd., San Vicente, Tarlac city
Telefax (045) 982 3734 Website: www.tsu.edu.ph

NOA #:2019-249

Date: August 15, 2019

NOTICE OF AWARD

KENNEDY T. HAW
Proprietor
POWER K CONSTRUCTION SUPPLY AND SERVICES
64 A. Regidor St., Sta. Cruz, Laguna

Dear Mr. Haw,


After careful evaluation and upon recommendation of the Bids and Awards Committee (BAC), following the RA 9184, we are happy to notify you that the project **Repainting of Roofing, Exterior Wall and Various Repair of CPAG Building** is hereby awarded to you as the Bidder with the Lowest Calculated and Responsive Bid at a contract price equivalent to **Two Million Nine Hundred Seventy Eight Thousand Two Hundred Sixty Pesos and 15/100 (PhP 2,978,260.15)**

You are therefore required to provide within ten (10) calendar days from the receipt of this Notice of Award, to formally enter into contract with us, and to submit the following as required by Republic Act 9184:

1. Performance Security in the form and the amount stipulated in the Instructions to Bidders
2. Insurance Coverage:
 - 2.1 Contractor's All Risk Insurance;
 - 2.2 Transportation to the Project Site of Equipment, Machinery, and Supplies owned by the Contractor;
 - 2.3 Personal injury or death of Contractor's employees; and,
 - 2.4 Comprehensive insurance for third party liability to Contractor's direct or indirect act or omission causing damage to third persons
3. List of Key Personnel, Schedule of S-Curve, Manpower Schedule, Construction Methods, Department of Labor and Employment, and PERT CPM.

Failure to enter into said contract or provide the Performance Security and Insurance coverage shall constitute as sufficient ground for cancellation of this award and forfeiture of your Bid Security.

Very truly yours,


DR. MYRNA Q. MALLARI
President

Conforme

KENNEDY T. HAW
Proprietor
POWER K CONSTRUCTION SUPPLY AND SERVICES
64 A. Regidor St., Sta. Cruz, Laguna

Date **August 23, 2019**

BAC RESOLUTION NO. CW021-2019
Repainting of Roofing, Exterior Wall and
Various Repair of CPAG Building